

Introduction to Turning

I-DEAS® Tutorials: Turning Projects

In this tutorial, you'll learn some basic techniques for machining turned parts. You'll learn how building a setup for turning is different from building a setup for milling.

Learn how to:

- build a turning setup
- create a rough turn operation
- machine undercuts

Before you begin...

Prerequisite tutorials:

- all tutorials under the Modeling Fundamentals menu
- Introduction to Generative Machining
- Building a Setup Assembly
- Generating In-process Stock and Checking Validity
- Working with Tools and Tool Catalogs
- Picking Holes
- Setting Machining Parameters for Hole-making Operations

The file you need for this tutorial is distributed with the product. You must copy it into your local directory.

Move to the local directory where you want to copy the file. Then:

In UNIX:


```
cp $SDRC_INSTL/examples/nc/ tut_turn_intro.arc .
```

In Windows use:

```
copy %SDRC_INSTL%\examples\nc\  
tut_turn_intro.arc .
```

If you can't copy the file, you may have to set up the variable needed to copy from the I-DEAS installation.

```
. sdrc_oadev
```

 If you can't access the file, contact your system administrator. The file may not be installed.


If you didn't start I-DEAS with a new (empty) model file, open a new one now and title it turning.




Open Model File form




Make sure you're in the following application and task:



Set your units to inches.




Import the archive file that contains the parts and tools that you need to complete this tutorial. Importing an archive file can take several minutes. Be patient.



Import Selections form



File Name Input form



The Manufacturing application quits, an informational message is displayed (the message will dismiss automatically), and the archive file is imported.

Import Archive File Status




Be sure to check the List region to be sure that the parts imported properly.



A second informational message is displayed (the message will dismiss automatically) and the Manufacturing application starts.

Create a job.



NC Job Create form

Job Name: Trailer Ball Job

OK

Add the part to the job.



Get

From Bin/Library

Select Part/Assembly form

OK

Recovery Point



Warning!

If you're prompted by I-DEAS to save your model file, respond:



Save only when the tutorial instructions tell you to—not when I-DEAS prompts for a save.

If you make a mistake at any time between saves and cannot recover, reopen your model file to the last save and start over from that point.


Hint

To reopen your model file to the previous save, press Control-Z.

For milling operations, you can build a very simple setup to complete your job. You merely align the part in relationship to the global coordinate system and generate your toolpaths.

For turning operations, however, the setup is a little more involved. You need to add machine and stock instances. A machine with an explicit machine coordinate system allows the software to guide the cuts. The stock enables the software to calculate the passes that compose the toolpath.

In the next few steps, you'll build a setup assembly from the following parts.




What: Modify the setup assembly.

How:




Setup Specification form

Name: Ball End Setup



What: Add the machine instance, then create a coordinate system on it.

How:



Add Machine form

 *Get Machine From Bin/Library*


Select Part/Assembly form


 tut_collet_chuck_2.5_inch
 *OK*

I-DEAS Warning

 *Dismiss*

Name form

Name: Machine Assembly
 *OK*

 Don't close the Machine Data: Lathe/Millturn, General form.

Things to notice

The coordinate system that you see is related to the original part and not the machine assembly. You can create a machine coordinate system by picking this existing coordinate system.

What: Create the machine coordinate system for the setup.

How:

Machine Data: Lathe/Millturn, General form




Type: Turn




Create MCS

1 origin of the coordinate system



Done

 Don't close the Machine Data: Lathe/Millturn, General form.

What: Pick the machine coordinate system for the setup. This defines the coordinate system as program zero.


How:

Machine Data: Lathe/Millturn, General form




Pick MCS

1 origin of the coordinate system



OK


Recovery Point



File
Save

What: Align the centerline of the part to the centerline of the machine.

How:




1 anywhere on the part




Move To

2 CP13

3 CC8

 After you've moved the part, don't quit out of this command. The steps continue on the next page.



What: Move the part away from the chuck along the centerline. The gap between the part and the chuck will allow a cutoff tool to pass between them in the next tutorial.

How:

1 anywhere on the part





2 *Move Along*

2 CL1 (centerline on the chuck)




2 Make sure the arrow is pointing towards the part by picking *Yes* or *No*.

 Translation Distance: .75



Result




Recovery Point

 *File*
Save

What: Add the stock to the setup assembly.

How:



Get



From Bin/Library


Select Part/Assembly form




tut_bar_stock_2.5_inch



OK




Recovery Point



*File
Save*

What: Move the stock into position for machining.

How:




1 anywhere on the stock




Move To

2 CP2

3 CC8

 After you've moved the stock, don't quit out of this command. The steps continue on the next page.



What: Move the stock in relationship to the part.

How:

1 anywhere on the stock




1 *Move Along*

2 CL1 (centerline on the chuck)



Make sure the vector is pointing towards the part by picking *Yes* or *No*.


1 *Yes*

 Translation Distance: 4.75




Recovery Point

 *File Save*



Result



What: Define in-process stock calculations for the setup.

How:




Setup Specification form

- ☒ *Enable In-Process Stock Calculations*
 - ☐ *Dismiss*
-

In the next steps, you'll create a rough turn operation to machine the ball end of the trailer hitch. After you generate the toolpath, you may notice that the tool doesn't completely cut the selected surfaces. Those uncut surfaces compose an *undercut*.

An undercut is a surface or collection of surfaces that has X or Z coordinates less than their adjacent surfaces. In this operation, you'll machine the part without cutting into the undercut. You'll use a stronger tool to rough the surface first.



What: Modify the opgroup by giving it a name.

How:



NC Job Planning form



OpGroup-1

OpGroup Specification form

Name: Rough Turning

 Don't close the OpGroup Specification form.

What: Create an operation to rough the outer diameter of the trailer ball's end.

How:

OpGroup Specification form



Operation Selection form




Category: Turning



Type: Rough Turn



Create

 Don't close the Operation Specification form.

What: Name the operation and pick the surfaces to be machined.

How:

Operation Specification form


Name: Rough without the Undercuts




1

2 shift pick

3 shift pick



 Don't close the Operation Specification form.

What: Retrieve the tool from the catalog.

How:

Operation Specification form



Turning Tool Specification form



Find... (next to *Combined Identifier*)



80 deg diamond



OK

Turning Tool Specification form



OK



Don't close the Operation Specification form.


What: Generate the toolpath.


How:

Operation Specification form



Recovery Point

 *File*
Save




Things to notice

The tool doesn't cut into the undercut.


In the next steps, you'll create a rough turn operation to machine the undercut. You'll use a lighter tool suited for undercutting.

You'll also learn how to view the clearance line as you animate the tool.



What: Create another rough turn operation. With this operation, you'll clear out the material remaining on the selected surfaces.

How:



OpGroup Specification form



Deselect *Rough without the Undercuts* by pressing the Control key and selecting *Rough without the Undercuts*.



Operation Selection form



Category: *Turning*



Type: *Rough Turn*



Create



Don't close the Operation Specification form.

What: Name the new operation and accept the preselected surfaces.

How:

Operation Specification form



Name: Rough with Undercuts



Things to notice

The surfaces you selected in the previous operation are highlighted by default. Accept these surfaces for the new operation.



 Don't close the Operation Specification form.

What: Retrieve the tool from the catalog.

How:

Operation Specification form



Turning Tool Specification form



Find... (next to *Combined Identifier*)

Item Selection form



55 deg diamond



OK



OK



Don't close the Operation Specification form.

What: Enable the operation to create undercuts on the diameters of the part.

How:

Operation Specification form



Machining Parameters form



Machine Undercuts on Diameters (on)



OK




Don't close the Operation Specification form.

What: Generate the toolpath.


How:

Operation Specification form




Things to notice

This operation removed most of the material remaining on the ball of the hitch. You can compare the toolpaths by picking *Show Previous* and *Show Next*.



What: Display the trailing clearance line, then animate the tool.

How:



Animate Tool form



Tool Display form



Clearance Line Display (on)




OK



Dismiss

Recovery Point



*File
Save*

Things to notice

Notice the uncut portion of the undercut is at the same angle as the trailing clearance line. The software can't violate the trailing clearance to remove material.

Warning!

Don't delete this model file once you're finished. You'll use this model file and job in the next tutorial.

Tutorial wrap-up

You've completed the Introduction to Turning tutorial.